

Test Report			Number	:	TWNC00285549	
Applicant:	Maymom, LLC No 20-7 Aly 19 LN333 ChungCheng RD Chunan			:	Nov 14, 2012	
Sample Description:						
One(1) group of submitted samples said to be :						
Item Name		:Breastpump Breast	shield			
Item No.		:M012 Batch 0001				
Quantity		:2 Pieces				
Vendor/Manufacturer		: Maymom, LLC				
Buyer's Name		: Maymom, LLC				
Country Of Origin		: Taiwan				
Goods Exported To		: USA				
Date Sample Received		:Nov 09, 2012				
Date Tes	t Started	:Nov 09, 2012				

## Test Conducted:

As requested by the applicant, for details please refer to attached pages.

Conclusion:		
Tested Sample	Standard	Result
Submitted Samples	Test For F.D.A. Regulation On	Pass
	Polypropylene	
	<ul> <li>As Per U.S. 21 CFR F.D.A.</li> </ul>	
	Regulation Part 177.1520	
	Clauses (c)(1.1) And (d)	

Authorized By: On Behalf Of Intertek Testing Services Taiwan Limited



K. Y. Liang Director

Page 1 of 3

Intertek Testing Services Taiwan Ltd. 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 114, Taiwan, R.O.C. 全國公證檢驗股份有限公司 114 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2410



Number : TWNC00285549

Test Conducted

## Test For F.D.A. Regulation On Polypropylene

As per the U.S. 21 CFR Food and Drug Administration part 177.1520 clauses (c)(1.1) and (d) with modification on density and melting point.

Test Component: Semitransparent Plastic

Test Item	Result	Limit
(A) Density	0.900	0.880 - 0.913
(By Sink-Float Method)		
(B) Melting Point	173°C	160 – 180℃(1.1a)
(C) Maximum Extractable Fraction In N-Hexane	0.43%(W/W)	6.4 %(W/W)
(D) Maximum Extractable Fraction In Xylene	2.57%(W/W)	9.8 %(W/W)

Remark: % = Percentage based on the residue by weight

## End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

Page 2 of 3

Intertek Testing Services Taiwan Ltd. 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 114, Taiwan, R.O.C. 全國公證檢驗股份有限公司 114 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2410



Number : TWNC00285549

Test Conducted



Page 3 of 3

Intertek Testing Services Taiwan Ltd. 8F., No. 423, Ruiguang Rd., Neihu District, Taipei 114, Taiwan, R.O.C. 全國公證檢驗股份有限公司 114 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2410