

Test Report

Number : TWNC01014020 Issue Date : Sep 02, 2021

Applicant: Maymom, LLC No. 20-7, Aly. 19, Ln. 333, Zhongzheng Rd., Zhunan Township, Miaoli County 350, Taiwan (R.O.C.)

Sample Description:

One (1) Group of Subn	nitted Samples Said To Be :
Item Name	: Breast Pump Parts_flange,cap
Item No.	: P012-F25,PP012-C
Manufacturer	: Maymom LLC
Buyer	: Maymom LLC
Country of Origin	: Taiwan
Goods Exported To	: USA,UK,CA,China,DE,AU,FR,IT,ES,AU,SG
Remark	: The batch No. of P012-F25,PP012-C is R20210722-5.
Date Sample Received	: Aug 25, 2021
Date Test Started	: Aug 26, 2021

Test Conducted:

As requested by the applicant, for details please refer to attached pages.

Authorized By: On behalf of Intertek Testing Services Taiwan Limited

alt Matt Wang

Matt Wang Director SERVICES TANKAN

Signed by:

homasChou

Thomas Chou Manager

Page 1 of 3



Intertek Testing Services Taiwan Ltd. 全國公證檢驗股份有限公司 8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 114690, Taiwan, R.O.C. 114690 台北市內湖區瑞光路 423 號 8 樓

Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com



Test Conducted :

Number : TWNC01014020

1. Overall Migration Test

With reference to Commission Regulation (EU) No. 10/2011 and its Amendments, the migration test was conducted once.

I. Test Condition: 40 $^{\circ}$ C for 2 hours

II. Test Result: Food Simulant: 50%(w/v) ethanol <u>Tested Sample</u> (1/2)

Result (mg/dm²) ND

Remarks: ND = Not detected Detection limit = 1 mg/dm² Solvents & test condition were selected based on applicant's request.

2. Specific Migration of Bisphenol-A (BPA) Test

With reference to European Commission regulation (EU) No. 10/2011 and its amendments, the migration test was conducted once.

I. Test Condition: 40° C for 2 hours

II. Test Result Food Simulant: 50%(w/v) ethanol <u>Tested Sample</u> (1/2)

Result (mg/kg food) ND

Remarks: ND = Not detected Detection limit = 0.05 mg/kg food Solvents & test condition were selected based on applicant's request.

Tested Components:

- (1) Semitransparent plastic part
- (2) Semitransparent plastic cap

Intertek Testing Services Taiwan Ltd. 全國公證檢驗股份有限公司 8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 114690, Taiwan, R.O.C. 114690 台北市內湖區瑞光路 423 號 8 樓

Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com

Page 2 of 3



intertek Total Quality. Assured.

Number : TWNC01014020

Sample photo:





End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: <u>http://www.intertek-twn.com/terms/</u>. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duites to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk

Reporting Statements of Conformity: Please note that the test results contain statement of conformity with the decision rules which are based on the specifications of customers, regulations and standards, and does not consider measurement uncertainty.



Intertek Testing Services Taiwan Ltd. 全國公證檢驗股份有限公司 8F., No. 423, Ruiguang Rd., Neihu District, Taipei, 114690, Taiwan, R.O.C. 114690 台北市內湖區瑞光路 423 號 8 樓 Tel: (+886-2) 6602-2888 · 2797-8885 Fax: (+886-2) 6602-2420 www.intertek-twn.com

